





CUT-CORES FOR HIGH APPLICATIONS

TYPICAL HYSTERESIS LOSS WITH GAP SIZE, $P_c(f, \mu)$



* Hysteresis losses are measured at room temperature, $25^{\circ}\text{C} \pm 3^{\circ}\text{C}$